



18/01/2023

Feature History Report

Page 2 of 2

Officer

Street: Blackshaw Road (22900509)

Report Type: Assessment

Street: Blackshaw Road (22900509)

Area: Tooting

Plot Number: 300,000.00

Feature Id - Location:

Feature Type: H-Cway Inspection Section

Contract Area: Highways LBW

Batch: 10037613 - Inspection Batch

Route: HW: Ad Hoc Inspection

Officer:

Date: 06/01/2023

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10085077	Tarmac breaking out 0.70m X 0.50m	06/01/2023	Outside 42	H116		Committed

Batch: 10036695 - Inspection Batch

Route: HW: Ad Hoc Inspection

Officer:

Date: 14/12/2022

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10083530	Tarmac breaking out 1.00m X 0.60m	14/12/2022	20.00m north of junction with kenlor road Opp. 88	H116		Committed

Batch: 10033927 - Inspection Batch

Route: I&E LBW Area 2B 03 Monthly

Officer:

Date: 20/10/2022

Observation Type	Code	Grade	Score	Notes
H-Carriageway	HCWY	Good	10.0000	
H-Left Kerb	HLKB	Not Assessed	.0000	
H-Right Kerb	HRKB	Not Assessed	.0000	

Batch: 10028255 - Inspection Batch

Route: HW: Ad Hoc Inspection

Officer:

Date: 22/06/2022

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10062441	Tarmac breaking out 2.0 m X 0.7m	22/06/2022	Opp. 66	H116		Committed

Batch: 10028254 - Inspection Batch

Route: HW: Ad Hoc Inspection

Officer:

Date: 22/06/2022

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10062439	Tarmac breaking out 1.0m X 0.7m	22/06/2022	Opp. 66	H116		Committed